



DAP NEDUET

Condition Assessment of Heritage Buildings - Karachi Declared as “Dangerous”

JUNE 2018

Structural Consultant



E: info@sadaffatima.com

W: www.sadaffatima.com

Contents

1. Introduction.....	5
2. Scope of Works.....	6
3. List of Dangerous Buildings of Karachi	6
4. Building Detail.....	7
4.1. Sherwala Mandir.....	7
4.2. Kausar Baba Dargah.....	13
4.3. OT 5/103.....	16
4.4. OT 6/86.....	19
4.5. OT 7/4.....	22
4.6. Dharam Das Mandir	24
4.7. Antarya Building	28
4.8. Calcutta Building.....	32
4.9. Jahangeer kothari.....	39
4.10. Jahangeer Mansion.....	45
4.11. Habib Bank Building	50
4.12. Farzana Mansion.....	51
4.13. Paracha Building.....	57
4.14. Fida Hussain.....	63
4.15. Khaliq Un Nisa	67
4.16. Karachi Muslim Restaurant	69
4.17. Sarang Building-Demolished.....	73
4.18. Feroz Pur Wala Market- Demolished	73
4.19. Sheeba Manzil-Demolished	73
4.20. Tayabi Manzil- Demolished	73
4.21. Tharyamal Nayandas	74
4.22. Rehmani Mansion	80
4.23. Devi Bai Building	86
4.24. Haji Hashim	92
4.25. NP 1/5	98
4.26. Rohana Banash Building.....	103
4.27. Sonamal Chandimal Building	108
4.28. NP 10/27	114
4.29. Hajra Building.....	117

4.30.	Jan Muhammad Building	122
4.31.	Mukhi Mansion	128
4.32.	Hussaini Building.....	132
4.33.	Quetta Wala Building	137
4.34.	Bhagwan Das Building	142
4.35.	SR 3/14.....	147
4.36.	Essaji Ibrahimji Building	153
4.37.	Old Shahani Building	157
4.38.	Ather Mansion	161
4.39.	Saify Electric.....	165
4.40.	Sami Chambers	169
4.41.	Dost Manzil.....	172
4.42.	Bhojraj Building.....	178
4.43.	Jiha Building	183
4.44.	Haque Building	186
4.45.	Hassan Ali Building.....	189
4.46.	SBQ 7/38.....	192
4.47.	Rainbow House.....	194
4.48.	Kanji Wasti Building	198
4.49.	Nabi Manzil	201
4.50.	United Bank Building	207
4.51.	SBQ 3/67.....	209
4.52.	Saiffee Building.....	210
5.	Summary of Conclusions.....	213
6.	Strengthening Levels	222
6.1.	Extensive strengthening Level.....	222
6.2.	Moderate Strengthening Level	225
6.3.	Minor Strengthening Level.....	226
7.	General Strengthening Guidelines	227

1. Introduction

Karachi, a Cosmopolitan city, the most populous city in Pakistan and third most populous city in the world is home to numerous heritage buildings which date back to 19th century. The vast majority of these stone workmanship building structures were built during British Raj. Conditions of most of these buildings is very bad now a days due to decay over a period of time, lack of maintenance and neglect on part of building owners.

SBCA (Sindh Building Control Authority) has declared almost 52 of heritage buildings as “Dangerous”. Any Building or structure whose strength, stability, serviceability, robustness and/or durability has been impaired due to any reason such as improper structural design and detailing, faulty and/or poor construction, decay, dilapidation, obsolescence, natural disasters or prompting deserting, due to all these reasons to a level, where it cannot be restored to its original status, classifies as Dangerous Building.

Culture/Heritage department thus initiated a study to assess if the existing heritage buildings can be restored by strengthening and repair. In this regard, M/S Sadaf Fatima was consulted by NED Architecture Department to inspect and survey the stability of these buildings from the aspect of being called “Dangerous”, i.e. to see if the buildings can be restored to their original strength by strengthening.

Site visits were conducted during the period of 27 March’2018 to 10 April’2018. At the time of initiation of visits, 7 buildings out of 52 buildings were inexistent being either demolished or collapsed.

Almost all of the buildings visited, same structural system was observed, that is, 15 to 24-inch-thick stone masonry walls with original timber plank flooring in localized area. Most of the floor area is replaced with reinforced concrete slab or precast slab system. In almost all of the buildings, interventions were observed ranging from moderate to high degree. In some buildings, new rooms have been added on top of original roof causing additional load on stone walls. Replacement of original timber flooring with RCC and precast has also deteriorated and have caused damage to existing original structure. At many places, it is suspected that floor finishes have been added on top of original one thus causing additional loading.

2. Scope of Works

The scope of work includes;

- On-site Visual survey of the building.
- Compilation of technical Report regarding the condition assessment of Buildings on the aspect of being Dangerous or otherwise.
- Suggesting Basic strengthening techniques

It must be noted that As-Built plans of most of the buildings were not available. The buildings were inspected physically and pictures were taken. Existing structural condition was noted for façade, internal walls, floors etc. and recommendation are based on visual inspection only.

3. List of Dangerous Buildings of Karachi

- | | |
|--------------------------------------|--------------------------------|
| 1. Sherwala mandir | 27. Sonamal Chandimal Building |
| 2. Kausar Baba Dargah | 28. NP 10/27 |
| 3. OT 5/103 | 29. Hajra Building |
| 4. OT 6/86 | 30. Jan Muhammad Building |
| 5. OT 7/4 | 31. Mukhi Mansion |
| 6. Dharam Das Mandir | 32. Hussaini Building |
| 7. Antarya Building | 33. Quetta Wala Building |
| 8. Calcutta Building | 34. Bhagwan Das Building |
| 9. Jahangeer Kothari | 35. SR 3/14 |
| 10. Jahangeer Mansion | 36. Essaji Ibraheemji Building |
| 11. Habib Bank Building | 37. Old Shahani Building |
| 12. Farzana Mansion | 38. Ather Mansion |
| 13. Paracha Building | 39. Saify Electric |
| 14. Fida Hussain | 40. Sami Chambers |
| 15. Khaliq un Nisa | 41. Dost Manzil |
| 16. Karachi Muslim Restaurant | 42. Bhojraj Building |
| 17. Sarang Building-Demolished | 43. Jiha Building |
| 18. Feroz Pur Wala Market-Demolished | 44. Haque Building |
| 19. Sheeba Manzil-Demolished | 45. Hassan Ali Building |
| 20. Tayabi Manzil-Demolished | 46. SBQ 7/38 |
| 21. Tharyamal Nayandas | 47. Rainbow House |
| 22. Rehmani Mansion | 48. Kanji Wasti Building |
| 23. Devi Bai Building | 49. Nabi Manzil |
| 24. Haji Hashim | 50. United Bank Building |
| 25. NP 1/5 | 51. SBQ 3/67 |
| 26. Rohana Banash Building | 52. Saifee Building |

4. Building Detail

4.1. Sherwala Mandir

General Information

Building Name: Sherwala Mandir
 Status: Partly Accessible
 Address: OT-02/137, GAO GALI, ATMA RAM ROAD
 Site visit Date: 10/4/2018
 Time: 11.07 am
 Building Number: 1
 Original Stories: Ground + 2 story

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	1868
3.	Approximate Age of Building:	150 yrs
4.	Intervention Status	
	Ground floor	No intervention
	First floor	<ul style="list-style-type: none"> - RCC Bracket Beams floor in most of places - Steel Girders to support the existing slab - Partition wall were added in residential apartment
	Second floor	Fully constructed
	Third floor	Partially constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with band beam-structure
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – Yes Side – Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories and partial third story, whereas additional third story on rest of the area has been added sometime later. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at a few locations and cracks were noticed on the first floor.
- Wide cracks were visible on front facade.
- Load Bearing Stone wall is a typical construction type followed.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off. Refer Plate-4, 5, 6 & 7.
- In central courtyard, Reinforced concrete construction, which was done later-on, was found in bad shape. The rebar is exposed. (Refer Plate 8 and 9)
- The ground floor is partially occupied by shop keepers doing cloth dying works the effects of seepage and different colors and chemicals used were also evident.
- The building is spread over wide area.
- Two floors had been added on top roof.
- It was observed that from entrance the left portion is tilted on left side and right side is tilted towards right side.



Plate-1: Front Façade- loose stone masonry can be noted at few places. Additional floor on top is also visible

Plate-2: Wide cracks at the rear façade of building



Plate-3 Right side



Plate-4: Timber slab in bad condition.



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Deformed timber slab resting on MS beams installed at later stage.



Plate-7: Bad condition of roof slab due to seepage.



Plate-8: Central court being turned into RCC construction



Plate-9: Bad condition of stone and RCC structure



Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages

4.2. Kausar Baba Dargah

General Information

Building Name: Cheti Bai Basarmal (Kausar Baba Dargah)
 Status: Accessible
 Address: OT-04/53, Rabia Basri (Thakur Dawara) Lane, V.I. Strandas Sukhramadas Street
 Site visit Date: 10/4/2018
 Time: 10.50 am
 Building Number: 2
 Original Stories: Ground

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	1930
3.	Approximate Age of Building:	88 yrs
4.	Intervention Status	
	Ground floor	No intervention
	First floor	- Wall at periphery were added. - Temporary roof sheeting
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Periphery load bearing wall with column elements
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	No
	Wall	No
	Columns	No
	Beam/Girder	-
	Floors	-

Observations

It was observed that;

- The original building is single storied structure.
- Originally, building had ground plus one story which was removed later making story height approx. 24 feet. Refer Plate-1.
- On front façade and side, tiles have been placed with finish. No portion of original stone wall is visible. Refer Plate-2, 3 & 4.
- All the stone masonry is repaired with mortar and cladded with tiles. Refer Plate-5 & 6.
- Current finishes do not show any kind of distress.



Plate-1: Front Façade- proper tiling works



Plate-2: side view all stone is covered with tile works



Plate-3: Side View



Plate-4: During-Construction view



Plate-5: stone exposed during construction



Plate-6: Walls and Columns completely covered with tiles and false ceiling hides the temporary roof laying above

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure appears to be in good condition.
- However, it is suspected that the mortar used for pointing and repair is cement mortar which is not good for stone integration in long run, hence it is recommended to guide the occupants/user of building to get the repair of building done with lime mortar.

4.3. OT 5/103

General Information

Building Name: OT-5/103
 Status: Inaccessible
 Address: OT-5/103, Adamjee Dawoodpota (Rampart) Road
 Site visit Date: 10/4/2018
 Time: 10.30 am
 Building Number: 3
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not available
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	vacant
	Roof	GI Sheets
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade (wooden jali and wall)	Front – yes Back – partial collapsed
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building used to be ground plus 3 stories, whereas additional roof was also in partial use. Refer Plate-1 for picture taken in 2007.
- The top floors were demolished by the residents recently. it appears that first floor is vacant. Refer Plate-2
- Building could be observed only from outside as it was inaccessible.
- Rear part of building appeared collapsed Refer Plate-3.
- From the back side of the building the stone seems to be loose and material has been filled in places to keep it intact. Refer Plate- 4.
- On front façade, loose stone masonry can be noticed at locations.

- First floor balcony is made of wood. The front projection seems to be deflected and the edges are broken. The brackets of projection are as per original construction but due to lack of maintenance they are in bad condition. Refer Plate-5 & 6
- Intervention appears to be limited to ground floor shops.



Plate-1: Front Façade- before demolition



Plate-2: Front Façade- after demolition

Plate-3: rare view shows apparent demolition





Plate-4: rare entrance



Plate-5: original wooden façade



Plate-6: cracks observed

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, partially collapsed building structure appears in non-workable condition.
- Moderate strengthening might be enough to make structure safe and workable for ground plus one story.
- Building could not be observed from inside, hence strengthening level suggested is based on visual inspection of façade only.
- Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions if present inside, should be removed
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster;
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.4. OT 6/86

General Information

Building Name: OT-6/86
 Status: Inaccessible
 Address: OT-6/86 JAI RAM DAS BAKOMAL ROAD, FAROOQ-E-AZAM LANE
 Site visit Date: 10/4/2018
 Time: 10:40 am
 Building Number: 4
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	None
	Roof	None
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure
6.	Typical Floor framing	Could not be observed
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – no Side – vertical crack at joint with other building
	Wall	yes
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories, no intervention at roof level was observed. Refer Plate-1.
- On front façade, horizontal cracks at top roof were observed in beam at lintel level and the slab projection. The stone wall seems to be intact. Refer Plate-1 & 4.
- Side elevation has a vertical crack generating from bottom and extending to the top story. Crack is at the joint of two adjacent buildings.
- The crack is almost 1” wide separating the building from its neighboring structure.

- Building is slender and appears to have tilted outwards creating gap with adjacent building.
- Shops are being made on ground.
- The building was inaccessible from inside and could be observed from outside only.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Vertical separation cracks at the right-side façade of building observed at rear side



Plate-3: Separation of Building



Plate-4: reinforced concrete slab in bad condition.



Plate-5: reinforced concrete slab in bad condition.

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure appears stable.
- However, since it could not be observed from inside, no comment can be made on the stability of internal structure.

4.5. OT 7/4

General Information

Building Name: OT-7/4
 Status: Façade only, inaccessible
 Address: OT-7/4, Khooshal Rai Lane
 Site visit Date: 10/4/2018
 Time: 12:00 pm
 Building Number: 5
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	--
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Approximate Damage Observed in Percentage	85%
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – yes Back – yes
	Wall	yes
	Beam/Girder	collapsed
	Floors	collapsed

Observations

It was observed that;

- The original building was ground + 3 stories. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations.
- Most floors have been collapsed leaving façade wall only.
- Few areas appeared to have been affected by fire.
- Termite infestation was also noticed a few places.
- In staircase area, which had collapsed, original timber construction for flooring was observed. Refer Plate-4.
- In central courtyard, Reinforced concrete construction could be noticed.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible

Plate-2: reinforced concrete column seen from outside



Plate-3: left side close up view of front façade



Plate-4: right side close up view of front

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building facade is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the façade stable.
- New Building structure inside will have to be constructed to join façade and make it stable.

4.6. Dharam Das Mandir

General Information

Building Name: Dharam Das Mandir
 Status: Partially collapsed
 Address: OT-9/93, Sukhdam Lane (Shah Abdullah Aleem Siddique Lane), Qazi Noor Mohammad Lane
 Site visit Date: 10/4/2018
 Time: 10:57 am
 Building Number: 6
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	vacant
	Roof	Temporary structure constructed with sheeting roof
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – Yes
	Wall	yes
	Slab	RCC, original Wooden
	Staircase	RCC

Observations

It was observed that;

- The original building is ground + 1 story with partial intervention on roof. Refer Plate-1.
- The ground floor is of 16ft clear height.
- Remains of arches are present where now shop shutters are being made.
- On front façade, stone masonry seems intact. Localized lintel shows sign of distress.
- Mortar of stone is being repaired in few locations.

- Right side elevation has a long diagonal crack.
- Rear part of building is collapsed. Refer Plate-3.
- Vertical cracks from side can be seen. The resident from neighbor claim that the debris is still falling off.



Plate-1: Front Façade- loose stone masonry can be noted at places. Additional floor on top is also visible



Plate-2& 3: side façade of the building collapsed



Plate-4: projection and bracket in original condition



Plate-5: vertical cracks on both floors in façade



Plate-6: Cracks around the arch



Plate-7: Inside view



Plate-8: Cracks at location of collapse

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Building was inaccessible and could be observed from outside only.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster.

4.7. Antarya Building

General Information

Building Name: Antarya Building
 Status: Façade only-inaccessible
 Address: W-02/40 NAJAMUDIN ROAD CHAND BIBI ROAD (PRINCESS STREET)
 Site visit Date: 28/3/2018
 Time: 10:35 am
 Building Number: 7
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	Non
	Second floor	Non
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front –No Back – Yes Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Collapsed

Observations

It was observed that;

- The original building is ground plus two stories with partial third story intervention. Refer Plate-1.
- On front façade, stone masonry seems to be crumbling at places.
- Rear part of building has deteriorated extensively.

- Building could be observed from outside only.
- Internal floors have been collapsed. Refer Plate-3.
- Timber beam and wooden slab is in bad condition. Refer Plate-1 to 4.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Wide cracks at the façade of building



Plate-3: Rear side



*Plate-4: slab in
bad condition,*



*Plate-5:
Concrete
construction, in
bad condition*



*Plate-6: broken
projections*

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.8. Calcutta Building

General Information

Building Name: Calcutta Building/Wadhmal Odhram Quarter
 Status: Partially collapsed
 Address: W-02/04 CHAND BIBI ROAD (PRINCESS STREET)
 Site visit Date: 28/3/2018
 Time: 10:00 am
 Building Number: 8
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with partial third story, whereas additional third story on rest of the area has been added sometime later. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations.
- Rear part of building was collapsed showing interventions at floor levels of building from first floor and onwards. Refer Plate-3.
- Comparison of Plate-2 and 3 clearly demonstrates the failure pattern of rear side. Wide cracks were visible (Refer Plate-2) along which failure happened later on.
- Load Bearing Stone wall is a typical construction of double-Wythe stone wall with small rubble stone in middle.
- In staircase area, which had collapsed, original timber construction for flooring was found. Refer Plate-3.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off. Refer Plate-4, 5, 6 & 7.
- In central courtyard, Reinforced concrete construction, which was done later-on, was found in bad shape. (Refer Plate 8 and 9)



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Wide cracks at the rear façade of building before collapse



Plate-3: After collapse of rear side



*Plate-4:
reinforced
concrete slab in
bad condition,
concrete cover
has fallen off.*



*Plate-5:
Concrete
construction
done later on,
in bad
condition*



*Plate-6: Loose
stone masonry is
visible*



Plate-7: Bad condition of roof slab due to punctures and seepage from plumbing lines



Plate-8: Central court being turned into RCC construction



Plate-9: Bad condition of reinforced concrete construction of central court



Plate-10: Bad condition of original timber flooring and walls at ground floor

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.9. Jahangeer kothari

General Information

Building Name: Jahangeer Kothari
 Status: Accessible
 Address: W-07/18 M.A. Jinnah (Bunder Road) Shahrah e Altaf Hussain (Napier Road)
 Site visit Date: 28/3/2018
 Time: 10.10am
 Building Number: 9
 Original Stories: Ground +1+Clock tower

S.no	Description	Observation
1.	As-Built Drawings availability:	Schematic plans
2.	Year of Construction:	1804
3.	Approximate Age of Building:	214
4.	Intervention Status	
	Ground floor	No intervention
	First floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girders
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes
	Slab	RCC, original Wooden
	Staircase	Original Wooden, RCC additional

Observations

It was observed that;

- Building appears to be in good condition. Refer Plate-1, 2
- Termite infestation was observed at a few locations. Refer Plate-6
- Floor decking is also in good condition.

- At few places, concrete cover is fallen off from RC projections. Refer Plate-8
- Staircase RCC beam has cracks in soffit. Refer Plate-9



Plate-1: Front Façade



Plate-2: Other view of Front Façade



Plate-3: Left side façade



Plate-4: Projection inside the court yard



Plate-5: Original projection still intact in place



*Plate-6:
Termite
infestation near
main entrance.*



*Plate-7: Stone
masonry being
punctured for
various reasons*



*Plate-8: Concrete
cover fallen off*



*Plate-9: Bad
condition of Beam
above stair*



*Plate-10: Central
court*



*Plate-11: Façade
Masonry*



*Plate-12:
condition of
original roof*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears in good and stable condition.
- Minor repair work can restore the original building structure to its former glory.

4.10. Jahangeer Mansion

General Information

Building Name: Jahangeer Mansion
 Status: Rear Block accessible
 Address: W-06/57 M.A. Jinnah (Bunder Road) Shivdas Chandumal Road
 Site visit Date: 27/3/2018
 Time: 11:21 am
 Building Number: 10
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Schematic
2.	Year of Construction:	1922
3.	Approximate Age of Building:	96
4.	Intervention Status	
	Ground floor	Banks
	First floor	- In Balconies
	Second floor	
	Third floor	
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard building in 2 blocks
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – Yes Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The main building is in two blocks and is connected from side via Façade frame structure.
- Front Block is G+3 Story with partial 4th story, and is in good condition. Refer Plate-1 and 2.
- Rear Block 2 G+3 Story with full 4th story intervention and is partially collapsed Refer Plate-3
- Rear Block entrance shows sign of distress with broken stair case and other collapsed story structural elements. Refer Plate-4
- In most of areas, where original slab is been encountered, is in bad condition.
- In most places the reinforced concrete floor is being laid later on. Refer Plate-6 & 9



Plate-1: Front Façade- in good condition



Plate-2: Wide cracks at the rear façade of building before collapse

Plate-3: After collapse of rear side



Plate-4: reinforced concrete slab in bad condition, concrete cover has fallen off.



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Loose stone masonry is visible



Plate-7: Bad condition of roof slab due to punctures and seepage from plumbing lines



Plate-8: Central court being turned into RCC construction



Plate-9: Bad condition of reinforced concrete construction of central court



Plate-10: Bad condition of original timber flooring and walls at ground floor

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Front Block of Building structure appears in good condition and localized repairs might be required.
- Rear block building structure is partially collapsed, whereas, the rest of area require moderate level strengthening to make structure stable.
- Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions, if any, should be removed
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Localized internal MS Angle frame

4.11. Habib Bank Building

General Information

Building Name: Habib Bank Building
Status: Demolished

4.12. Farzana Mansion

General Information

Building Name: Farzana Mansion
 Status: Partially Collapsed
 Address: MR-1/79, Kucchi Wada Lane No. 3
 Site visit Date: 28/3/2018
 Time: 11.57 am
 Building Number: 12
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	Non
	Second floor	Non
	Third floor	Partially constructed
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – No Side – partial collapsed
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes
	Wall	Stone
	Beam	In part RCC & in part original wooden rafters
	Slab	RCC, original Wooden
	Staircase	Original Wooden

Observations

It was observed that;

- The original building is ground plus two stories with partial intervention at roof is being observed.
- All the projections from the front have been collapsed. Steel sheets are being used in the roof as a repair measure.
- The mortar in stone masonry is being corroded.
- In top story intervention is observed where the temporary roof is being supported by steel girder.
- The original wooden slab and timber beams are deflecting at various places.
- The concrete cover has been corroded in various places.
- On front façade, crack was observed from lintel to sill level on first floor to second floor. loose stone masonry can be noticed at many locations.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off.



*Plate-1: side Façade-
Partially Collapsed*



Plate-2: original wooden structural elements in deteriorated condition



Plate-3: Front Façade



Plate-4: Timber slab in bad condition



*Plate-5:
Concrete
construction
done later on,
in bad
condition,
concrete cover
has fallen off.*



*Plate-6:
Exposed
rebar's subject
to rusting*



Plate-7: Bad condition of roof slab due to seepage from plumbing lines



Plate-8: Projection plaster being fallen off



*Plate-9: Stair in
Bad condition*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.13. Paracha Building

General Information

Building Name: Paracha Building
 Status: Accessible
 Address: MR-1/91, Kucchi Wada Lane No. 3
 Site visit Date: 28/3/2018
 Time: 12:00 pm
 Building Number: 13
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with third story addition sometime later. Refer Plate-1.
- On front façade, no loose stone masonry can be noticed at many locations.
- The over-all condition of the building is very good. Few locations need repair works.
- The stair case is of wood and need minor repair work.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Side View



Plate-3: Front View



*Plate-4:
Condition of
wooden deck*



Plate-5: Original condition of wooden roof



*Plate-6: Staircase
in bad condition*



*Plate-7: Bad
condition of roof
slab due to
punctures and
seepage from
plumbing lines*



Plate-8: wooden deck condition inside



Plate-9: Bad condition wooden flooring



Plate-10: Bad condition of original timber flooring

Conclusions and Recommendations

Based on the observations, it is concluded that;

- The over-all condition of the building appears stable as condition of stone masonry is ok. However, at few locations, such as staircase and wooden floor, repair works are needed.
- The stair case is of wood and need minor repair work.
- Top roof slab made in RCC need extensive repair.

4.14. Fida Hussain

General Information

Building Name: Fida Hussain
 Status: Inaccessible
 Address: MR-1/151, M. A. Jinnah (Bundar) Road, Marriot Road
 Site visit Date: 28/3/2018
 Time: 12.21 pm
 Building Number: 14
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	- Advertisement board
	Second floor	- None
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories. Refer Plate-1.
- On front façade, no sign of distress was observed. However, a big advertisement board can be observed hanging from the façade. Refer Plate-2.
- Rear part of building also seems in better condition except from the parapet which is partly damaged. Refer Plate-3.
- The original wooden slab seems to be in good condition. Refer Plate-4
- The staircase is also sound. Refer Plate-5.
- In roof slab projection concrete cover is been fallen off from places. Refer Plate-6.
- Inside condition also look in quite good condition. Refer Plate 7



Plate-1: Front
Façade



Plate-2: façade of building



Plate-3: rear side



Plate-4: slab condition,



Plate-5: Stair case in original condition



Plate-6: slab projection in bad condition



Plate-7: Inside condition

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Building appears to be in stable condition.
- Minor repair work is needed at few locations.

4.15. Khaliq Un Nisa

General Information

Building Name: Khaliq un Nisa
 Status: Inaccessible from inside
 Address: MR-2/4, Marriott Road, Fakhr Matri (Newnham) Road
 Site visit Date: 28/3/2018
 Time: 12.42 am
 Building Number: 15
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	- Steel Girders have been added
	Second floor	- Steel Girders have been added
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	-
7.	Visible Structural cracks/deterioration in following framing elements	NO

Observations

It was observed that;

- The original building is ground plus three stories with fourth floor addition having temporary roof top. Refer Plate-1, 2 & 5.
- On front façade, no sign of distress was observed. Refer Plate-2.
- Rear part of building also seems in better condition except shops intervention on ground floor. Refer Plate-3.
- The staircase is also in good condition. Refer Plate-4.
- Loose stone masonry due to MS girder (for floors) intervention observed in side wall. Refer Plate-5.



Plate-1: back side Façade



Plate-2: front façade of building



Plate-3: rear side



Plate-4: stair



Plate-5: left side elevation

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Building appears to be in good condition.
- Minor repair work is needed at few locations.

4.16. Karachi Muslim Restaurant

General Information

Building Name:	Karachi Muslim Restaurant
Status:	Accessible
Address:	MR-2/31, Abdul Majid Sindhi Road, Daulat Ram Road
Site visit Date:	28/3/2018
Time:	12.35 pm
Building Number:	16
Original Stories:	Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Restaurant
	First floor	- Sheeting temporary structure on partial roof
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	RCC Slab
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	Yes
	Floors	No

Observations

It was observed that;

- The original building is ground plus 1 story with partial mezzanine and intervention at roof. Refer Plate-1.
- On front façade, no loose stone masonry can be noticed at any locations except for very minor cracks in the RCC projection. Refer Plate-2.
- Slab of first floor seems in good condition, proper repair works are evident. Refer Plate-3.
- Partial intervention at roof top was observed with temporary sheeting roof. Refer Plate-4.
- Horizontal cracks were observed a few places on roof RCC beams. Refer Plate-5 & 6.



*Plate-1: Front
Façade-*



*Plate-2: minor
cracks in slab
projection*



*Plate-3:
reinforced
concrete slab
condition,*



*Plate-4:
Temporary roof
above*



Plate-5: horizontal cracks in roof beams



Plate-6: horizontal crack in the RCC element

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Minor repair works are needed, especially in reinforced concrete projections and floor beams.

4.17. Sarang Building-Demolished

4.18. Feroz Pur Wala Market- Demolished

4.19. Sheeba Manzil-Demolished

4.20. Tayabi Manzil- Demolished

4.21. Tharyamal Nayandas

General Information

Building Name: Pana Chand (Tharyamal Nayandas), Dasandash Nayandas
 Status: Partially Collapsed
 Address: MAC-2/19, Moosa Street Off Rehmat Ullah Street, Eisa St.
 Site visit Date: 28/3/2018
 Time: 02.53 pm
 Building Number: 21
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Concept Sketch
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	
	Second floor	
	Third floor	Remains of structure above roof
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab and RCC at corridor area
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	collapsed

Observations

It was observed that;

- The original building is ground plus 3 story with partial fourth story intervention. Refer Plate-1.
- On front façade, no loose stone masonry can be noticed however at few locations vertical cracks have been observed at 3 locations from lintel to sill. Refer Plate-2 and 3.
- The ground floor is in better condition.
- Part of Floor inside have been collapsed and traces of fire were also observed at one location.



Plate-1: Front Façade



Plate-2: Vertical Cracks at few location



Plate-3: Front façade masonry intact



Plate-4: slab condition at ground



*Plate-5:
Original timber
beam intact*



*Plate-6:
Concrete cover
fallen off at
places*



Plate-7: Bad condition of slab due to punctures and seepage from plumbing lines



Plate-8: Slab deflecting



Plate-9: Bad condition of reinforced concrete construction of central court



Plate-10: collapsed slab at 2nd floor



Plate-10: Bad condition of slab



Plate-10: collapsed slab at 3rd floor

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Overall condition of supporting system of building appears stable, however, reinforced concrete construction (slabs/beams) need repair.
- Interventions such as top most story added later should be removed.
- Façade has cracks at few locations but do not appear dangerous, should be repaired immediately however.

4.22. Rehmani Mansion

General Information

Building Name: Rehmani Mansion / Bombay Bazaar
 Status: Façade only
 Address: MAC-3/12, Aga Khan (Harris) Road, Adamjee Dawood Pota (Rampart) Road
 Site visit Date: 28/3/2018
 Time: 03:20 pm
 Building Number: 22
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	- none.
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	No
	Floors	Removed

Observations

It was observed that;

- The original building is ground plus 1 story. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations.
- At first floor, the building seems to be tilted at right.
- The framing elements slab and walls are being removed on first floor causing the façade to deteriorate.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2: Wide cracks at first floor level



Plate-3: mortar has been eroded



*Plate-4: slab
removed at roof*



*Plate-5:
condition of
wooden slab at
ground floor*



*Plate-6: traces of
seepage*



*Plate-7: masonry
needs repairment
works*



*Plate-8: left side
façade*



*Plate-9: Bad
condition of
plaster and
masonry at first
floor*



Plate-10: stair removed

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure seem unstable,
- Extensive strengthening is required
- Repair works are needed like pointing in joints, and repair of deck/floor works
- Masonry has eroded at few places and patch work is needed to strengthen the weak areas.

4.23. Devi Bai Building

General Information

Building Name: Devi Bai Building
 Status: Partially Collapsed - Accessible
 Address: MAC-6/4, Young Husband Road off G. Allana (Tahilaram Khemchand) Road
 Site visit Date: 28/3/2018
 Time: 02.08 pm
 Building Number: 23
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	- Non
	roof	- Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	Yes
	Columns	Yes
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story with intervention at roof. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations.
- The concrete cover is crumbling in various locations. Budge in column is observed. Deflection in beams can also be observed.
- Traces shows that most damages is due to seepage and lack of maintenance.
- Stair Case condition is also bad



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: bad condition of masonry in façade



Plate-3: side elevation condition



*Plate-4: vertical
cracks observed*



*Plate-5:
Concrete
construction
beam deflecting*



*Plate-6: concrete
in bad condition*



*Plate-7: Bad
condition of
timber slab due
seepage from.*



*Plate-8: RCC
construction
deteriorating*



*Plate-9: cracks
observed above
lintel*



Plate-10: bad condition of masonry wall

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Major strengthening is required to make the structure stable.
- Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.24. Haji Hashim

General Information

Building Name: Haji Hashim
 Status: Partially Collapsed
 Address: MAC-7/57, Macchi Miani Road
 Site visit Date: 28/3/2018
 Time: 03.49 pm
 Building Number: 24
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	- Partition wall were added in residential apartment.
	Second floor	Fully constructed
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – partial collapsed Side – No
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 3 stories with 4th story intervention added sometime later. Refer Plate-1 & 3.
- Front façade and side façade, stone masonry seems intact at all locations. Refer Plate-1 & 2.
- Rear part of building was collapsed showing interventions at floor levels of building from first floor and onwards. Refer Plate-5.
- In most of areas, reinforced concrete floor, was found in bad condition with concrete cover fallen off.
- In central courtyard, Reinforced concrete construction, was found in bad shape.



Plate-1: Front Façade- top story added later on can be seen



Plate-2: right side façade



Plate-3: crack in wall of intervention at roof



*Plate-4:
original deck in
bad condition,*



*Plate-5:
Concrete
construction
collapsed*



*Plate-6: bad
condition of
timber slab*



*Plate-7: concrete
cover fallen off*



Plate-8: Central court being repaired and turned into RCC construction



Plate-9: collapsed area



Plate-10: Bad condition of original timber slab

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Façade is in better condition but the internal structure, specially reinforced concrete floors added later on, are in very bad condition.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.25. NP 1/5

General Information

Building Name: NP-1/5
 Status: Façade only
 Address: NP-1/5, Janar D.B Road, off Nawab Mahabat Khan (Embankment) Road
 Site visit Date: 10/4/2018
 Time: 11:33 am
 Building Number: 25
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
	Second floor	-
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – collapsed Side – Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with third story added sometime later. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many location and vertical cracks can be observed.
- The building façade seems to be deflected back and building seems to be tilted left side.
- Slabs have been collapsed inside.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Side façade of building



Plate-3: Front façade



Plate-4: timber slab in bad condition,



Plate-5: steel girders installed to support existing slab



*Plate-6: Loose
stone masonry is
visible*



*Plate-7: slab
and stair
collapsed*



Plate-8: Bad condition of facade in front

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, original building structure appears to be in need of moderate level of strengthening. However, additional floor on top should be removed to avoid any risk to existing structure due to additional stresses by its load.
- No major cracks in stone walls were noticed, hence it is anticipated that pointing work/joint repairs will strengthen the masonry walls.
- Interventions from roof top should be removed.
- Internal staircase and wooden decks need to be repaired as they are in very bad condition.

4.26. Rohana Banash Building

General Information

Building Name:	ROHANA BANASH ASHRADI BUILDING
Status:	Stable Structures
Address:	NP-9/18, Mohammad Shah Street, Ghulam Shah Street
Site visit Date:	28/3/2018
Time:	11.04 am
Building Number:	26
Original Stories:	Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	-
	Second floor	-
	Third floor	Partial structure above
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 3 stories with fourth third story, added sometime later. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations. Vertical cracks are observed from lintel to sill level. Growth of plantation is also being observed.
- Original timber construction for flooring was found.

- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off.
- In central courtyard, Reinforced concrete construction, which was done later-on, was found in bad shape.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Wide cracks at façade



Plate-3: side façade



Plate-4: reinforced concrete slab in bad condition, concrete cover has fallen off.



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Loose stone masonry is visible



Plate-7: Bad condition of roof slab due to punctures and seepage from plumbing lines



Plate-8: Central court being turned into RCC construction



Plate-9: condition of reinforced concrete construction of central court

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears to be stable.
- Cracks are noticed in façade, which should be repaired.
- Concrete construction done later on is in bad condition and needs major repair.

4.27. Sonamal Chandimal Building

General Information

Building Name: Sonamal Chandimal Building
 Status: Partially Collapsed
 Address: NP-9/45, Mohammad Shah Street, off Shahrah-e-Altah Hussain (Napier Road)
 Site visit Date: 28/3/2018
 Time: 11.03 am
 Building Number: 27
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story with partial interventions added sometime later. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations.
- All floors are collapsed
- The front façade is being separated from the structure behind.



Plate-1: Front Façade-



Plate-2: front elevation



Plate-3: Wide cracks at the side façade of building



Plate-4: slab collapsed



Plate-5: slab crumbling



Plate-6: Bad condition of original timber flooring and walls at ground floor



Plate-7: Bad condition of masonry



*Plate-8: Central
court plantation
with in the wall*



*Plate-9:
strengthening
done at any later
stage*



Plate-10: slab collapsed

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Front façade however, seems in good condition, but has separated from rest of building as a crack has developed along the height.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.28. NP 10/27

General Information

Building Name: NP 10/27
 Status: Partially Collapsed
 Address: NP-10/27, Chuba street, Munji Khetsi Street, Off Old Market Road.
 Site visit Date: 28/3/2018
 Time: 11:31 am
 Building Number: 28
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
	Second floor	- Intervention in floor above.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front - Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 2 stories with partial third story, whereas additional third story on rest of the area has been added sometime later. Refer Plate-1.
- Disjointing/loosening of Stone masonry is noticed at façade.
- Internal building part has collapsed leaving façade unsupported to its remaining height.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Wide cracks at the façade of building



Plate-3: Wide cracks

Plate-4: Rear side



*Plate-5 & 6:
collapsed*



Conclusions and Recommendations

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Building Façade however appears in better condition but need repairs as cracks and disjoining of stone masonry is observed a few locations.
- Extensive strengthening is required to make the overall structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls.

4.29. Hajra Building

General Information

Building Name: Hajira Building
 Status: Façade Only
 Address: RC-3/24, Visram Kara Lane, Marwaree Lane, off Nishtar (Lawrence) Road
 Site visit Date: 10/4/2018
 Time: 02:27 am
 Building Number: 29
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
	Second floor	-
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 2 stories. Refer Plate-1.
- Façade wall is intact with intervention of masonry wall on top level, rest of the structure inside has collapsed.
- Façade wall is also in bad shape.



Plate-1: Front Façade



Plate-2: Wide cracks at the façade of



Plate-3: façade rear side



Plate-4: timber slab in bad condition,



Plate-5: slab deflecting



*Plate-6: Loose
stone masonry is
visible*



*Plate-7:
masonry
collapsed*



*Plate-8: masonry
at rare façade in
bad condition*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Only façade wall is intact with masonry intervention on top, whereas internal structure has collapsed. Hence the façade is also unstable in current condition and needs major repairs to hold it.

4.30. Jan Muhammad Building

General Information

Building Name: Jan Muhammad Building (Khatija Bai Building)
 Status: Partially Collapsed
 Address: RC-4/147, off Nabi Bux Road, Kullianji St., Bhawanji St.
 Site visit Date: 10/4/2018
 Time: 02.45 am
 Building Number: 30
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – Yes
	Wall	yes
	Columns	No
	Beam/Girder	collapsed
	Floors	collapsed

Observations

It was observed that;

- The original building is ground plus 1 story with partial roof story, Refer Plate-1.
- Only façade is remaining and since framing elements slab and walls are being removed on first floor causing the façade to deteriorate.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Wide cracks at the rear façade of building before collapse



Plate-3: After collapse of rear side



*Plate-4:
reinforced
concrete slab
in bad
condition,
concrete cover
has fallen off.*



*Plate-5:
Concrete
construction
done later on,
in bad
condition*



Plate-6: Loose stone masonry is visible



Plate-7: Bad condition of roof slab due to punctures and seepage from plumbing lines



Plate-8: Central court being turned into RCC construction



Plate-9: Bad condition of reinforced concrete construction of central court



Plate-10: Bad condition of original timber flooring and walls at ground floor

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Internal floors have collapsed, which need major rebuilt efforts.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.31. Mukhi Mansion

General Information

Building Name: Mukhi Mansion
 Status: Stable Structures
 Address: RC-7/3B, M. A. Jinnah (Bunder) Road, Haridas Lalji Road
 Site visit Date: 27/3/2018
 Time: 11.08 am
 Building Number: 31
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
	Second floor	-
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories Refer Plate-1.
- On front façade, no signs of distress were observed.
- The ground floor slab and beams were also intact.
- Building appears to be in good condition.



Plate-1: Front
Façade-



Plate-2: front facade



Plate-3: side façade



*Plate-4: reinforced
concrete slab and
beam*




Plate-5: stair case



Plate-6: side elevation

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Building appears to be in good condition
- Minor repair works are needed to restore the building to its original glory.

4.32. Hussaini Building

General Information

Building Name: Hussaini Building / Hussaini Manzil
 Status: Better Condition
 Address: RC-10/19/5, Ranchore Road, Aslam Road
 Site visit Date: 10/4/2018
 Time: 01.03 pm
 Building Number: 32
 Original Stories: Ground + 4

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First, Second, third , fourth floor	- Partition wall were added in residential apartment.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- Building appears to be in good condition. Refer Plate-1, 2, 3.
- Floor decking is also in good condition.
- At few places, concrete cover is fallen off from RC projections due to poor maintenance.
- Staircase was replaced with RCC and is in good condition.



*Plate-1: Front
Façade-*



Plate-2: Façade



Plate-3: Façade



Plate-4: Stair case



*Plate-5:
Concrete
construction
done later on,*



Plate-6: poor maintenance



Plate-7: façade wall inside



*Plate-8: Central
court*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building appears to be stable.
- Minor repair work in reinforced concrete construction can restore the structure.

4.33. Quetta Wala Building

General Information

Building Name: Quetta Wala Building
 Status: Stable Structures
 Address: RC-11/1A, CHAND BIBI ROAD (PRINCESS STREET),
 Sant Tukaram Street
 Site visit Date: 10/4/2018
 Time: 01.16 pm
 Building Number: 33
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	- Partition wall were added in residential apartment.
	Second floor	- Partition wall were added in residential apartment.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – Yes Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at a few locations and cracks were noticed on the first floor.

- Vegetation was visible on front façade widening the crack from its origin.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off.
- In central courtyard, Reinforced concrete construction, which was done later-on, was found in bad shape. The rebar is exposed.
- The ground floor is partially occupied by shop keepers
- The building is spread over wide area.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2: Wide cracks at the façade of building



Plate-3: Masonry condition at façade



Plate-4: Bad condition of original timber flooring and walls



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Central court being turned into RCC construction



Plate-7: Bad condition of reinforced concrete construction of central court



*Plate-8:
reinforced
concrete slab in
bad condition,
concrete cover
has fallen off.*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not dangerous but needs major repairs.
- Extensive strengthening of internal reinforced concrete structure is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.34. Bhagwan Das Building

General Information

Building Name: Bhagwan Das Building
 Status: Stable Structures
 Address: RC-11/11, Hardas Street, Aslam Road, off Aslam (Hiralal Ganatra) Road
 Site visit Date: 10/4/2018
 Time: 01:52 am
 Building Number: 34
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	<ul style="list-style-type: none"> - Partition wall were added in residential apartment. - Addition on Roof
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story with partial intervention of the roof story, added sometime later. Refer Plate-1.
- Façade appears to be ok but wooden projections/balconies were in bad shape.
- On Rear façade from inside plantation can be observed growing from the wall causing cracks to form Refer Plate-3.
- The vertical crack is observed inside and the timber slab is deflecting in various places.

- In most of areas, reinforced concrete floor was found in bad condition with concrete cover fallen off.
- In central courtyard, Reinforced concrete construction, which was done later-on, was found in bad shape.



Plate-1: Front Façade-



Plate-2: Front facade



Plate-3: After collapse of rear side



Plate-4: reinforced concrete slab in bad condition, concrete cover has fallen off.



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Loose stone masonry is visible



Plate-7: Bad condition of roof slab due to punctures and seepage from plumbing lines



Plate-8: Central court being turned into RCC construction



Plate-9: Bad condition of reinforced concrete construction of central court

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Building is in bad condition from inside and need major repair of internal structure to give it overall stability.
- Façade masonry can be repaired with minor repair works and should be connected to internal structure rigidly.

4.35. SR 3/14

General Information

Building Name: SR 3/14
 Status: Partially Collapsed
 Address: SR-3/14, Sharah-e-Liaquat (Frere Road), Aiwan-e-Tijarat (Nicol Road)
 Site visit Date: 10/4/2018
 Time: 10.12 am
 Building Number: 35
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention temporary structures
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at a various locations and cracks were also noticed.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off.
- In major part of building, roof structure inside has been removed making façade wall unsupported.
- The building is spread over wide area.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2: Main arch for entrance



Plate-3: inside the facade



*Plate-4:
masonry wall is
damaged due to
intervention of
structural steel
for bill board*



*Plate-5: Bad
condition of
original timber
flooring and
walls at ground
floor*



Plate-6: Concrete construction done later on, in bad condition



Plate-7: intervention at the back



*Plate-8: entrance
arch from inside*



*Plate-9: slab
broken*



Plate-10: Loose masonry visible

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as extra floor finishes where present, masonry walls or additional built-ups, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.36. Essaji Ibrahimji Building

General Information

Building Name: Essaji Ibrahimji Building
 Status: Façade Only-Inaccessible from inside
 Address: SR-9/14, Fiaz Mohammad Futeh Ali Road
 Site visit Date: 10/4/2018
 Time: 12.32 pm
 Building Number: 36
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground floor only. Refer Plate-1
- Stone seems to be loose and mortar in joints have been eroded.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2 & 3: Wide cracks at the façade of the building



Plate-4: Loose stone masonry is visible



Plate-5: Loose stone masonry is visible



Plate-6: Loose stone masonry is visible

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Being only ground floor, the structure can be made stable by pointing of mortar in joints and/or stone repair works.
- Roof can also be replaced with new framing/sheets to restore the building.

4.37. Old Shahani Building

General Information

Building Name: Old Shahani Building
 Status: Partially collapsed/dismantled
 Address: RB-3/8-4, Teckchand Udhamdas Road, off Muhammad Bin Qasim (Bunder) Road
 Site visit Date: 27/3/2018
 Time: 10:07 am
 Building Number: 37
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories. Refer Plate-1.
- Front façade seems intact and in good location.
- The stair is collapsed so no access is available.
- Roots/vegetation are noticed to be protruding from the wall.



Plate-1: Front Façade-



Plate-2: Masonry needs repair in few places



Plate-3: slab of portion seems collapsed



Plate-4: timber slab is in good condition,



Plate-5: stair is inaccessible



Plate-6: masonry wall in bad condition

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears stable however, is in need of major repairs.
- Loose stone masonry should be repaired.
- Interventions if any should be removed.

4.38. Ather Mansion

General Information

Building Name:	Ather Mansion
Status:	Inaccessible
Address:	RB-3/24, Maulana Din Mohammad Wafai (Strachan) Road
Site visit Date:	27/3/2018
Time:	09:57 am
Building Number:	38
Original Stories:	Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	- RCC steel girder floor in most of places - Partition wall were added in residential apartment.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story with partial second story. Refer Plate-1.
- On front façade, loose stone masonry can be noticed a few locations can be repaired.
- The RCC slab has been destroyed at locations.

- The building exterior seems to be tilting and bulging with cracks at left.
- Front entrance slab is on steel girders but in bad shape.
- Intervention on roof with RCC beam frame.
- Rear façade part of building seems collapsed.
- There is a tree damaging the wall in the back.
- The OHWT is a future extension but in bad condition the building it-self feels tilting.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2: Wide cracks at the façade of building



Plate-3: walls seems bulging



Plate-4: tree out grown from the wall tearing the wall apart



Plate-5: portion of building collapsed



Plate-6: Loose stone masonry is visible

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is not in useable condition.
- It appears that major strengthening works are required to make structure stable.

4.39. Saify Electric

General Information

Building Name: Saify Electric
 Status: Inaccessible
 Address: RM-6/73, Sharah-e-Liaquat (Frere Road), Yousuf Street
 Site visit Date: 10/4/2018
 Time: 12.38 pm
 Building Number: 39
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	-
	Second floor	- Intervention at roof of temporary structure.
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories with partial third story intervention added sometime later. Refer Plate-1.
- On front façade, the structure seems intact except for few projections that need maintenance works.
- Side elevation is also in good condition of building. Refer Plate-3.
- Original timber construction is in very good.



Plate-1: Front Façade-



Plate-2: front elevation of building



Plate-3: Side elevation



*Plate-4:
projection in
their original
condition intact*



*Plate-5: plaster
fallen off due to
lack of
maintenance*



Plate-6: reinforcement of original projections exposed

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears to be in better condition.
- The balcony structures are in bad condition and are susceptible to collapse, as reinforcement of RCC projections have corroded and concrete cover has fallen.
- Internal side could not be observed hence, condition is unknown.

4.40. Sami Chambers

General Information

Building Name: Sami Chambers
 Status: Accessible
 Address: RB-6/108, M. A. Jinnah (Bunder) Road, Arambagh Road
 Site visit Date: 27/3/2018
 Time: 11.40 am
 Building Number: 40
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	- Non
	Second floor	- Partial new construction
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Back – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories with partial new construction on 2nd story has been added sometime later. Refer Plate-1.
- Front façade seems intact and in good condition
- The girder is installed in second floor below RCC slab
- Over all structure is in good condition.



Plate-1: Front Façade-. Additional floor on top is also visible



Plate-2: front façade



Plate-3: side elevation



Plate-4: timber slab in good condition,



Plate-5: Concrete construction done later on, in bad condition



Plate-6: Concrete cover damage

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears to be in stable condition.
- No wide cracks were noticed in façade at the time of visit.
- Reinforced concrete construction at some places was in bad conditions and needed repair.

4.41. Dost Manzil

General Information

Building Name: Dost Manzil
 Status: Accessible
 Address: RB-8/4, Robson Rd., Mohammad Bin Qasim (Burnes) Rd.
 Site visit Date: 27/3/2018
 Time: 10.24 am
 Building Number: 41
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	- CC parapet
	Second floor	- CC parapet
	Third floor	- CC parapet
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with partial third story, whereas additional third story on rest of the area has been added sometime later. Refer Plate-1.
- On front façade, one vertical crack was observed.
- On left side elevation the projection has heavy interventions.
- The entrance at the arch needs repairs.

- The opening made in the stone masonry needs to be closed.
- In most of areas, reinforced concrete floor laid later on, was found in bad condition with concrete cover fallen off.
- Stone masonry found in bad condition as mortar at joint has eroded.
-



*Plate-1: Front Façade-
Additional floor on top is
also visible*



Plate-2: intervention on projection



Plate-3: bad condition of stair



*Plate-4:
reinforced
concrete slab in
bad condition,
concrete cover
has fallen off. It
has be
strengthened
still in very bad
condition*



*Plate-5:
deteriorated
stone and
mortar*



*Plate-6: Loose
stone masonry is
visible*



Plate-7: Interventions inside



Plate-8: Stair at upper level



Plate-9: opening in stone walls needs to be filled



Plate-10: back side wall

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, main building structure appears unstable and need major repairs, especially balconies.
- Reinforced concrete construction is in bad shape in many places and needs strengthening.
- Interventions at projections should be removed.

4.42. Bhojraj Building

General Information

Building Name: Bhojraj Building
 Status: Partly accessible
 Address: RB-10/21, Babar (Ramchandra Temple) Road, Gidumal Lekhray Road
 Site visit Date: 27/3/2018
 Time: 01:35 pm
 Building Number: 42
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Third floor	Fully constructed
5.	Type of Building Construction:	Original load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories with complete third story added sometime later projecting outwards. Refer Plate-1.
- Bhojraj building is in better condition than the neighboring building, hence it is suspected that due to its neighborhood building, it is declared dangerous.
- Reinforced concrete construction at some places is found in bad condition.
- Additional floor on top has been built sometime later.



Plate-1: Front Façade- Additional floor on top is also visible



Plate-2: façade of building



Plate-3: side elevation



Plate-4: new construction inside



Plate-5: concrete cover damage



*Plate-6: RCC
beam intervention*



*Plate-7: RCC
steps in good
condition*



*Plate-8: damage
due to seepage*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure appears in stable condition.
- No major cracks or deterioration was noticed anywhere in stone masonry.
- Reinforced concrete construction needs repair at some places.

4.43. Jiha Building

General Information

Building Name: Jiha Building
 Status: Partially Collapsed
 Address: PR-2/27, M.A. Jinnah (Bunder) Road, Sir Agha Khan II (Garden) Road
 Building Number: 43
 Original Stories: Ground + 2

S.no	Description	Observation
8.	As-Built Drawings availability:	Not provided
9.	Year of Construction:	Unknown
10.	Approximate Age of Building:	Unknown
11.	Intervention Status	
	Ground floor	shops
	First floor	- Non
	Second floor	- Non
12.	Type of Building Construction:	Original Load bearing stone wall on exterior
13.	Typical Floor framing	No slabs existing
14.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories with no slab intact, only façade wall is free standing. Refer Plate-1.



Plate-1: Front Façade



Plate-2: façade of building



Plate-3: side elevation



Plate-4: new construction inside



Plate-5: concrete cover damage

Conclusions and Recommendations

Based on the observations noted, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.44. Haque Building

General Information

Building Name: Haque Building
 Status: Inaccessible
 Address: SB-6/34, Raja Ghazanfar Ali Road (Somerset Street)
 Sheikhchand Street
 Site visit Date: 10/4/2018
 Time: 05.19 pm
 Building Number: 44
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
	First floor	-
	Second floor	-
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus two stories. Refer Plate-1.
- The building is itself in very good condition.
- Structure was inaccessible from inside but apparently, overall condition looks good from outside.



*Plate-1: Front
Façade-*



Plate-2&3: Different exterior views



*Plate-4:
structure in
good condition*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- No apparent sign of distress could be noticed from outside.
- Building looks in stable condition.
- Since inside of building could not be visited, so no comment can be made on structural condition.

4.45. Hassan Ali Building

General Information

Building Name: Hassan Ali Building
 Status: Apparently stable, inaccessible from inside
 Address: SB-7/10, Zaibunnisa (Elphinstone) Street, Shahrah-e-Iraq (Clarke Street)
 Site visit Date: 10/4/2018
 Time: 04:36 am
 Building Number: 45
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First and second floor	- Temporary structure for advertisement
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Side – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus one story. An additional story has been constructed on top. Refer Plate-1.
- Stone masonry visible on first level seems to be loose and plaster has fallen off.
- Building could not be accessed to observe from inside.



Plate-1: Front Façade- loose stone masonry can be noted at many places.



Plate-2 Plaster fallen off from the façade of building



Plate-3: side elevation



*Plate-4:
reinforced
concrete slab in
bad condition,
concrete cover
has fallen off.
Plaster been
weathered.*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, it appears that building is stable, but needs repairs
- Building could not be observed from inside hence no comment can be made.

4.46. SBQ 7/38

General Information

Building Name: SBQ 7/38
 Status: Inaccessible
 Address: W-02/04 CHAND BIBI ROAD (PRINCESS STREET)
 Site visit Date: 10/4/2018
 Time: 05.10 am
 Building Number: 46
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – No Side – No
	Wall	No
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus 1 story. Refer Plate-1.
- On front façade, stone masonry appeared to be in good condition with slightly loose condition of masonry at few locations.
- Rest building seems to be in good condition.
- The building was inaccessible for observation from inside.



Plate-1: Front Façade-

Conclusions and Recommendations

Based on the observations, it is concluded that;

In existing condition, building structure appears to be in stable condition from outside.

4.47. Rainbow House

General Information

Building Name: Rainbow House
 Status: Partly inaccessible
 Address: SB-7/40, Zaibunnisa (Elphinstone) Street, Albert Street
 Site visit Date: 10/4/2018
 Time: 05.06 pm
 Building Number: 47
 Original Stories: Ground + 2

S.no	Description	Observation
1.	As-Built Drawings availability:	Not available
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	-
	Second floor	-
5.	Type of Building Construction:	Original Load bearing stone wall
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder
7.	Visible Structural cracks/deterioration in following framing elements	
	Facade	Front – Yes Side – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two story. Refer Plate-1.
- The building is in bad condition over all, part of wooden Jali work collapsed and stone masonry in loose condition, especially at top floor.
- All timber beams and slabs are damaged and dislodged.
- The stone masonry is crumbling.

Plate-1: Front Façade- wooden jali work in bad condition.



Plate-2: part of stair inside.





*Plate-3: stair
broken*



*Plate-4: Façade
in bad condition*



Plate-5: Condition of wooden floor from inside

Conclusions and Recommendations

Based on the observations, it is concluded that;

- In existing condition, building structure is not stable and is susceptible to failure/collapse.
- Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique.
- Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls,
- Strengthening techniques can be adopted, including but not limited to;
 - a. Pointing of mortar in existing stone masonry joints,
 - b. Application of mesh plaster
 - c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.

4.48. Kanji Wasti Building

General Information

Building Name: Kanji Wasti Building
 Status: Partially accessible
 Address: SB-7/48, Albert Street, Stalker Street
 Site visit Date: 10/4/2018
 Time: 04.46 am
 Building Number: 48
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shop
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with third story added sometime later. Refer Plate-1.
- Façade is in good condition but inside the structure is crumbling the slab and beams are deflecting.



Plate-1: Front Façade-



Plate-2: timber slab.



Plate-5: slab above stair



Plate-6: Loose planks

Conclusions and Recommendations

Based on the observations, it is concluded that:

- Building appears to be in better condition from outside, however, deck/floor needs to be replaced/repared.

4.49. Nabi Manzil

General Information

Building Name: Nabi Manzil
 Status: Accessible
 Address: SB-7/75, Woodburn Street, Stalker Street
 Site visit Date: 10/4/2018
 Time: 04.40 pm
 Building Number: 49
 Original Stories: Ground + 3

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	Shops
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front - No Side - Yes
	Wall	Yes
	Columns	No
	Beam/Girder	No
	Floors	No

Observations

It was observed that;

- The original building is ground plus 3 stories. Refer Plate-1.
- Front façade appears intact and in good condition.
- Side elevation has a crack and it seems the wall is bulging.
- Over all building is in very good condition minor repair works needed.



*Plate-1: Front
Façade-*



Plate-2: side elevation little wall seems bulging



Plate-3: front side



*Plate-4:
reinforced
concrete slab in
good condition,*



*Plate-5:
Concrete
construction
done later on,*



*Plate-6: slab
damage due to
seepage*



*Plate-7: Bad
condition of
timber deck*



Plate-8: stair



*Plate-9: Bad
condition
reinforced
concrete
construction*



*Plate-10: loose
stone masonry*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Building appears to be in good condition from outside.
- From inside, stone walls appear intact, however, repair work is needed in floor decks and staircases.

4.50. United Bank Building

General Information


Building Name: United Bank Building
 Status: Inaccessible
 Address: SB-7/9, Raja Ghazanfar Ali Road (Somerset Street)
 Site visit Date: 10/4/2018
 Time: 05.15 am
 Building Number: 50
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	shops
	First floor	-
5.	Type of Building Construction:	Original Load bearing stone wall on exterior
6.	Typical Floor framing	
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes
	Wall	Yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus 1 story. Refer Plate-1.
- On front façade, loose stone masonry can be noticed at many locations due to intervention of MS girders.
- Roof appears to have been collapsed or removed.



*Plate-1: Front
Façade-*

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Front façade of building appears to be in better condition and need minor repairs, however, it appears to have no support from inside as roof deck appears to have been collapsed.
- Roof structure to be repaired and rebuilt.

4.51. SBQ 3/67

General Information

Building Name:

Parsi Mortuary

Status:

Demolished

4.52. Saifee Building

General Information

Building Name: Saifee Building
 Status: Inaccessible
 Address: CL-1/1, Dr. Ziauddin Road, Elander Road
 Site visit Date: 28/3/2018
 Time: 04.14 pm
 Building Number: 52
 Original Stories: Ground + 1

S.no	Description	Observation
1.	As-Built Drawings availability:	Not provided
2.	Year of Construction:	Unknown
3.	Approximate Age of Building:	Unknown
4.	Intervention Status	
	Ground floor	No intervention
	First floor	<ul style="list-style-type: none"> - RCC Pre-cast and steel girder floor in most of places - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Second floor	<ul style="list-style-type: none"> - Columns and beams were added in courtyard - Partition wall were added in residential apartment.
	Third floor	Fully constructed
5.	Type of Building Construction:	Original Load bearing stone wall on exterior with beam-column structure in middle courtyard
6.	Typical Floor framing	Original wooden slab with mortar on wooden girder after intervention RCC beam-column framing
7.	Visible Structural cracks/deterioration in following framing elements	
	Façade	Front – Yes Back – partial collapsed Side – No
	Wall	yes
	Columns	No
	Beam/Girder	Yes
	Floors	Yes

Observations

It was observed that;

- The original building is ground plus two stories with partial third story, whereas additional third story on rest of the area has been added sometime later. Refer Plate-1.
- Part of the building was accessible which was cladded and plastered
- Diagonal cracks in the plaster of Face was observed in 2 locations.
- Rare side of the building which could only be observed from outside which as not plastered and loose stone masonry with weathered mortar was observed.



Plate-1: Front Façade- loose stone masonry can be noted at many places. Additional floor on top is also visible



Plate-2: Side View



Plate-3: Crack on side of wall



Plate-4: crack in stone masonry wall

Conclusions and Recommendations

Based on the observations, it is concluded that;

- Part of the building where crack has appeared needs strengthening/repair immediately.
- Rest of the building appears in good shape and requires minor strengthening works to restore it.
- Building could not be observed from inside hence condition is not known

5. Summary of Conclusions

S.No.	Building Name	Conclusion
1	Sherwala mandir	<ul style="list-style-type: none"> - In existing condition, <u>building structure is not stable and is susceptible to failure/collapse.</u> - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ul style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
2	Kausar Baba Dargah	<ul style="list-style-type: none"> - In existing condition, building structure appears to be in good condition. - However, it is suspected that the mortar used for pointing and repair is cement mortar which is not good for stone integrity in long run, hence it is recommended to guide the occupants/user of building to get the repair of building done with lime mortar.
3	OT 5/103	<ul style="list-style-type: none"> - In existing condition, partially collapsed building structure appears in non-workable condition. - Moderate strengthening might be enough to make structure safe and workable for ground plus one story. - Building could not be observed from inside, hence strengthening level suggested is based on visual inspection of façade only. - Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions if present inside, should be removed - Strengthening techniques can be adopted, including but not limited to; <ul style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
4	OT 6/86	<ul style="list-style-type: none"> - In existing condition, building structure appears stable. - However, since it could not be observed from inside, no comment can be made on the stability of internal structure.

Condition Assessment of Heritage Buildings

5	OT 7/4	<ul style="list-style-type: none"> - In existing condition, building facade is not stable and is susceptible to failure/collapse. - Extensive strengthening is required to make the facade stable. - New Building structure inside will have to be constructed to join facade and make it stable.
6	Dharam Das Mandir	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Building was inaccessible and could be observed from outside only. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ul style="list-style-type: none"> c. Pointing of mortar in existing stone masonry joints, d. Application of mesh plaster.
7	Antarya Building	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ul style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
8	Calcutta Building	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to;

Condition Assessment of Heritage Buildings

		<ul style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
9	Jahangeer Kothari	<ul style="list-style-type: none"> - In existing condition, building structure appears in good and stable condition. - Minor repair work can restore the original building structure to its former glory.
10	Jahangeer Mansion	<ul style="list-style-type: none"> - Front Block of Building structure appears in good condition and localized repairs might be required. - Rear block building structure is partially collapsed, whereas, the rest of area require moderate level strengthening to make structure stable. - Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions, if any, should be removed, - Strengthening techniques can be adopted, including but not limited to; a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Localized internal MS Angle frame
11	Habib Bank Building	Demolished
12	Farzana Mansion	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; d. Pointing of mortar in existing stone masonry joints, e. Application of mesh plaster f. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
13	Paracha Building	<ul style="list-style-type: none"> - The over-all condition of the building appears stable as condition of stone masonry is ok. However, at few locations, such as staircase and wooden floor, repair works are needed. - The stair case is of wood and need minor repair work. - Top roof slab made in RCC need extensive repair.
14	Fida Hussain	<ul style="list-style-type: none"> - Building appears to be in good condition.

Condition Assessment of Heritage Buildings

		- Minor repair work is needed at few locations.
15	Khaliq un Nisa	- Building appears to be in good condition. - Minor repair work is needed at few locations.
16	Karachi Muslim Restaurant	- Minor repair works are needed, especially in reinforced concrete projections and floor beams.
17	Sarang Building	Demolished
18	Feroz Pur Wala Market	Demolished
19	Sheeba Manzil	Demolished
20	Tayabi Manzil	Demolished
21	Tharyamal Nayandas	- Overall condition of supporting system of building appears stable, however, reinforced concrete construction (slabs/beams) need repair. - Interventions such as top most story added later should be removed. - Façade has cracks at few locations but do not appear dangerous, should be repaired immediately however.
22	Rehmani Mansion	- In existing condition, building structure seem unstable, - Extensive strengthening is required - Repair works are needed like pointing in joints, and repair of deck/floor works - Masonry has eroded at few places and patch work is needed to strengthen the weak areas.
23	Devi Bai Building	- In existing condition, building structure is not stable and is susceptible to failure/collapse. - Major strengthening is required to make the structure stable. - Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
24	Haji Hashim	- In existing condition, building structure is not stable and is susceptible to failure/collapse.

		<ul style="list-style-type: none"> - Façade is in better condition but the internal structure, especially reinforced concrete floors added later on, are in very bad condition. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to: <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
25	NP 1/5	<ul style="list-style-type: none"> - In existing condition, original building structure appears to be in need of moderate level of strengthening. However, additional floor on top should be removed to avoid any risk to existing structure due to additional stresses by its load. - No major cracks in stone walls were noticed, hence it is anticipated that pointing work/joint repairs will strengthen the masonry walls. - Interventions from roof top should be removed. - Internal staircase and wooden decks need to be repaired as they are in very bad condition.
26	Rohana Banash Building	<ul style="list-style-type: none"> - In existing condition, building structure appears to be stable. - Cracks are noticed in façade, which should be repaired. - Concrete construction done later on is in bad condition and needs major repair.
27	Sonamal Chandimal Building	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Front façade however, seems in good condition, but has separated from rest of building as a crack has developed along the height. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster

		c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
28	NP 10/27	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Building Façade however appears in better condition but need repairs as cracks and disjuncting of stone masonry is observed a few locations. - Extensive strengthening is required to make the overall structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls.
29	Hajra Building	<ul style="list-style-type: none"> - Only façade wall is intact with masonry intervention on top, whereas internal structure has collapsed. Hence the façade is also unstable in current condition and needs major repairs to hold it.
30	Jan Muhammad Building	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Internal floors have collapsed, which need major rebuilt efforts. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ul style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
31	Mukhi Mansion	<ul style="list-style-type: none"> - Building appears to be in good condition - Minor repair works are needed to restore the building to its original glory.
32	Hussaini Building	<ul style="list-style-type: none"> - In existing condition, building appears to be stable. - Minor repair work in reinforced concrete construction can restore the structure.
33	Quetta Wala Building	<ul style="list-style-type: none"> - In existing condition, building structure is not dangerous but needs major repairs. - Extensive strengthening of internal reinforced concrete structure is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of

Condition Assessment of Heritage Buildings

		<p>existing walls/floors before proceeding with any strengthening technique.</p> <ul style="list-style-type: none"> - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
34	Bhagwan Das Building	<ul style="list-style-type: none"> - Building is in bad condition from inside and need major repair of internal structure to give it overall stability. - Façade masonry can be repaired with minor repair works and should be connected to internal structure rigidly.
35	SR 3/14	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse. - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as extra floor finishes where present, masonry walls or additional built-ups, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
36	Essaji Ibraheemji Building	<ul style="list-style-type: none"> - Being only ground floor, the structure can be made stable by pointing of mortar in joints and/or stone repair works. - Roof can also be replaced with new framing/sheets to restore the building.
37	Old Shahani Building	<ul style="list-style-type: none"> - In existing condition, building structure appears stable however, is in need of major repairs. - Loose stone masonry should be repaired. - Interventions if any should be removed.
38	Ather Mansion	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is not in useable condition. - It appears that major strengthening works are required to make structure stable.
39	Saify Electric	<ul style="list-style-type: none"> - In existing condition, building structure appears to be not dangerous.

Condition Assessment of Heritage Buildings

		<ul style="list-style-type: none"> - The balcony structures are in bad condition and are susceptible to collapse, as reinforcement of RCC projections have corroded and concrete cover has fallen. - Internal side could not be observed hence, condition is unknown.
40	Sami Chambers	<ul style="list-style-type: none"> - In existing condition, building structure appears to be in stable condition. - No wide cracks were noticed in façade at the time of visit. - Reinforced concrete construction at some places was in bad conditions and needed repair.
41	Dost Manzil	<ul style="list-style-type: none"> - In existing condition, main building structure appears unstable and need major repairs, especially balconies. - Reinforced concrete construction is in bad shape in many places and needs strengthening. - Interventions at projections should be removed.
42	Bhojraj Building	<ul style="list-style-type: none"> - In existing condition, building structure appears in stable condition. - No major cracks or deterioration was noticed anywhere in stone masonry. - Reinforced concrete construction needs repair at some places.
43	Jiha Building	<ul style="list-style-type: none"> - In existing condition, <u>building structure is not stable and is susceptible to failure/collapse.</u> - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
44	Haque Building	<ul style="list-style-type: none"> - No apparent sign of distress could be noticed from outside. - Building looks in stable condition. - Since inside of building could not be visited, so no comment can be made on structural condition.
45	Hassan Ali Building	<ul style="list-style-type: none"> - In existing condition, it appears that building is stable, but needs repairs - Building could not be observed from inside hence no comment can be made.
46	SBQ 7/38	<ul style="list-style-type: none"> - In existing condition, building structure appears to be in stable condition from outside.
47	Rainbow House	<ul style="list-style-type: none"> - In existing condition, building structure is not stable and is susceptible to failure/collapse.

		<ul style="list-style-type: none"> - Extensive strengthening is required to make the structure stable. Strengthening measures to be done with careful methodology which will include propping of existing walls/floors before proceeding with any strengthening technique. - Interventions should be removed such as the additional floor on top and extra floor finishes where present, to decrease the dead load on existing walls, - Strengthening techniques can be adopted, including but not limited to; <ol style="list-style-type: none"> a. Pointing of mortar in existing stone masonry joints, b. Application of mesh plaster c. Introducing internal mild steel frame within the building to secure the occupants from fatal damages.
48	Kanji Wasti Building	<ul style="list-style-type: none"> - Building appears to be in better condition from outside, however, deck/floor needs to be replaced/repared.
49	Nabi Manzil	<ul style="list-style-type: none"> - Building appears to be in good condition from outside. - From inside, stone walls appear intact, however, repair work is needed in floor decks and staircases.
50	United Bank Building	<ul style="list-style-type: none"> - Front façade of building appears to be in better condition and need minor repairs, however, it appears to have no support from inside as roof deck appears to have been collapsed. - Roof structure to be repaired and rebuilt.
51	SBQ 3/67	Demolished
52	Saifee Building	<ul style="list-style-type: none"> - Part of the building where crack has appeared needs strengthening/repair immediately. - Rest of the building appears in good shape and requires minor strengthening works to restore it. - Building could not be observed from inside hence condition is not known


6. Strengthening Levels


6.1. Extensive strengthening Level

In Extensive Strengthening Level,

- Steel structure frame is to be introduced to jacket the existing stone masonry walls and to form a frame within the original structure, tied-up together in a way, that if any sliding/settlement or tilting initiate in the stone wall structure, the frame work should hold the walls together and redistribute the load to the rest of the frame elements. Refer Sketch-A below.
- Cracks should be sealed with soft mortar (lime mortar) applied over metal lath which is to be nailed to the stone walls. Refer Sketch-B & D
- Additional built up on floor should be removed.
- Any interventions/additions should be removed.
- Light weight partition to be used for future development.
- Existing floor/deck elements should be repaired/replaced/cleaned, strengthened if required, and Mild Steel elements to be painted with Anti-Rust Paint.
- Façade walls if found tilted outwards, should be anchored with tie rods. These tie rods will need to be connected to internal MS frame to give anchorage.
- MS angle frame to be installed in door and window frames to secure the openings. Refer Sktech-C

Note: For the structures, which require Extensive Strengthening Level, Professional Structural Engineer should be involved to design Strengthening/Retrofitting works.






Sketch B: Wall repair detail

6.2. Moderate Strengthening Level

In Moderate Strengthening Level,

- MS angle frame to be installed in door and window frames to secure the openings. Refer Sketch-C
- MS frame (as shown in Sketch A) might be required in localized area.
- Cracks should be sealed with soft mortar (lime mortar) applied over metal lath which is to be nailed to the stone walls. Refer Sketch-D.
- Existing floor/deck elements should be repaired/replaced/cleaned, strengthened if required, and Mild Steel elements to be painted with Anti-Rust Paint.
- Additional built up on floor should be removed.
- Any interventions/additions should be removed.
- Light weight partition to be used for future development.




Sketch C: Typical Door/Window Opening Strengthening Detail

6.3. Minor Strengthening Level

In Minor Strengthening Level,

- MS angle frame to be installed in localized opening locations. Refer Sketch-C.
- Cracks should be sealed with soft mortar (lime mortar) applied over metal lath which is to be nailed to the stone walls. Refer Sketch-D.
- Existing floor/deck elements should be repaired/replaced/cleaned, strengthened if required, and Mild Steel elements to be painted with Anti-Rust Paint.
- Additional built up on floor should be removed.
- Any interventions/additions should be removed.
- Light weight partition to be used for future development.



**PART ELEVATION OF EXISTING
STONE WALL**

Sketch D: Wall Repair Detail

7. General Strengthening Guidelines

Mild Steel Internal Frame:

- Mild steel internal frame can consist of MS angles at corners of walls connected through MS strips running all round at lintel level. These MS angles and strips would be bolted to existing stone masonry at approx. 18 to 24 inch center to center (Refer Sketch-A).

Plaster

- Where needed, walls shall be plastered with 1" th. cement: lime: sand mortar (1:1:4). All existing surfaces shall be thoroughly cleaned and a layer of 18 SWG GI metal lathe shall be fixed prior to plaster with the help of steel nails. Appropriate spacers shall be placed to ensure that metal lathe is at the center of mortar. The plastered surfaces shall be cured with water thrice a day for at least 10 days.

Steel Structure

1. All structural steel sections to be used in strengthening works, should be cleaned by sand blast, galvanized, painted with one coat of epoxy primer and 2 coats of epoxy paint each.
2. All structural steel sections to have minimum yield strength of 36 ksi (252mpa) conforming to ASTM A 36.
3. use minimum 1/4" th. full weld through e-70 electrode unless noted otherwise. Specifications of other electrodes available to be submitted to engineer for approval.
4. All MS base plates to be 1/4" thick unless noted otherwise.
5. Welding works to conform to ANSI AWS D 1.1 code.